

PU020028  
 K.L. GRIMES, ET AL.  
 SHEET 1 OF 9  
 METHOD AND SYSTEM FOR  
 MAINTAINING EVEN TUBE BURN-IN  
 Vincent E. Duffy  
 Telephone (317) 587-4019  
 Express Mail Label EJ648049888US




FIG. 1

PU020028  
 K.L. GRIMES, ET AL.  
 SHEET 2 OF 9  
 METHOD AND SYSTEM FOR  
 MAINTAINING EVEN TUBE BURN-IN  
 Vincent E. Duffy  
 Telephone (317) 587-4019  
 Express Mail Label EJ648049888US




FIG. 2

PU020028  
K.L. GRIMES, ET AL.  
SHEET 3 OF 9  
METHOD AND SYSTEM FOR  
MAINTAINING EVEN TUBE BURN-IN  
Vincent E. Duffy  
Telephone (317) 587-4019  
Express Mail Label EJ648049888US




FIG. 3




FIG. 4




FIG. 5




FIG. 6

PU020028  
K.L. GRIMES, ET AL.  
SHEET 7 OF 9  
METHOD AND SYSTEM FOR  
MAINTAINING EVEN TUBE BURN-IN  
Vincent E. Duffy  
Telephone (317) 587-4019  
Express Mail Label EJ648049888US




FIG. 7




FIG. 8






FIG. 9